CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
EAST QUARTER Corner of Section 15	Township 141, Range 29, 5thp.M.
STATE OF MINNESOTA, County ofCASS	
At the corner location shown on the sketch:	
Ø On 9/18/80 found g marked GLO brass cap monument in place as set in 1918.	
M loft manument as found [] lawared manufact. [] and a law lot law	
☑ left monument as found, □ lowered monument, □ removed monument (explain)	
Onplaced a	
SKETCH OF REFERENCE TIES	
SKETOTI OF KELEKOLE TIES	
4	
-N-	
Nail in 8" Cedar .	
N 58.W 18.11'	Nail in 10" Cedar
Scribed	. N 78 E 16.88'
* Scribed	
··· O	
Nail in	
8" Cedar	
S 86 W 11.12' Scribed	
SCI-Ibed	
	1918-GLO-BT 20". Cedar
·	' S 30 E 128 links
	*
	BEARINGS ARE APPROXIMATE
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under	County of Can
my direct supervision.	I hereby certify that this document was filed in
Lay H. Alexan 12-29-81	the Co. Recorders office at 9:36 A.M. on the 31 day of Dec. A.D., 1981
Registration No. 12684	County Recorder Beneath Hardinh
Land Surveyor, Professional Engineer	By M S ,Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 260 998

Statement of Evidence:

- U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 2" Birch N 22 W 16 links and 4" Poplar S 60 E 48 links.
- U.S. General Land Office dependent resurvey reestablished this corner by proportional distance between section corners. No evidence was found of the original post or bearing trees. An iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked:

 14" Cedar S 30 E 128 links and 4" Tamarac S 87 W 54 links. Notes show corner in cedar swamp.
- USFS technician L. Witthoeft found the GLO brass cap monument in place and the cedar bearing tree.
- 1980 USFS technician W. Olson found the GLO brass cap monument in place up 10" in good condition and the cedar bearing tree. Three new bearing trees were marked and are shown on this certificate. A steel sign post was set 4.0' north of the corner.
- 1981 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- On Dec. 22, I visited the corner and found items as per the 1980 USFS report. The Cedar BT had-partially over grown scar with scribing clearly visible. Also found a live 12" Tamarac at the approximate bearing and distance called for in 1918. However, no visible evidence was found that it was the bearing tree and I did not cut it open. I accepted the monument found as marking the same position as when set in 1918 based on the Cedar BT.