Index	No	P-18

	Index No
	N OF GOVERNMENT CORNER 13,Township141,Range29,5thP.M.
STATE OF MINNESOTA, County ofCASS	
At the corner location shown on the sketch:	
☑ On 8/19/80 found a marked GLO	brass cap monument up 6".
☑ left monument as found, ☐ lowe	ered monument, \square removed monument (explain)
□ Onplaced a	
SKETCH OF F	REFERENCE TIES
Nail·in - 5" W. Oak	
N 68 W 23.88' Scribed	
Nail in 12" W. Oak S 65 W 12.28' Scribed	·o
Nail. 6" W. S:43. Scrib	Oak W 35.28' .
	BEARINGS ARE APPROXIMATE
Statement of evidence relative to this corner lo	cation is on back of page. 263904
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE COUNTY RECORDER County of
my direct supervision.	I hereby certify that this document was filed in the Co. Recorders office at $9:30 \text{ A} \cdot \text{.M.}$ on the
Day H. Stevenson 4-30-82 SIGNATURE DATE	County Recorder Bull Herbrich
Registration No. <u>1268</u> ← B Land Surveyor, □ Professional Engineer	1 _
☐ County Surveyor, ☐ County Engineer	By M S ,Deputy DOCUMENT NO. 26 3904

Statement of Evidence:	

U.S. General Land Office dependent resurvey established this corner. and an iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 10" Tamarac S 72-15 E 75 links

and 10" N. Pine N 3-15 W 96 links.

1980 USFS technician W. Olson found the marked GLO brass cap monument in place in good condition. No evidence was found of the 1918 bearing trees. Three new bearing trees were marked. A steel sign post was

set 4' west of the corner.

1981 County Surveyor's Records in the Recorder's Office were checked and no

resurvey information was found on this corner.

On Jan. 29, visited the corner and found items as per the 1980 USFS 1982 report. Snow depth prevented a detailed search for evidence of the

1918 bearing trees.

1918

On April 21, USFS technician C. Krause revisited the corner area and 1982 found the following evidence of the 1918 bearing trees: At N 3-15 W 63.4' found pine stump and log slaying on the ground and at \$ 72-15 E 49.5' found burned tamarac stump. The iron pipe is badly rusted and was found in 6" of water at the base of a slope.

Accepted the found monument as marking the same position as set in 1918.