

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 21, Township 144, Range 29, 5th P.M.

STATE OF MINNESOTA, County of CASS


At the corner location shown on the sketch:

On 11/25/80 found a GLO brass cap monument as set in 1926.
DATE

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



Nail in
18" W. Pine
West. 107.45'
Scribed



Nail in
14" W. Pine
S 32. E 15.19'
Scribed



Nail in
7" W Oak
S 54. W 55.75'
Scribed



Nail in
7" W. Oak.
S 13. W 68.01'
Scribed

BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Nancy H. Stevenson 9-15-82
SIGNATURE DATE

Registration No. 12684

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

279378
OFFICE OF THE COUNTY RECORDER
County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 4:00 P. .M. on the 10 day of Dec. A.D., 1984

County Recorder Chondine Kayler

By MS, Deputy

DOCUMENT NO. 279378

Statement of Evidence:

- 1873 U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 7" Ash S 53 E 28 links, 10" Poplar N 67 E 21 links, 9" Poplar N 33 W 34 links, and 6" Maple S 52 W 31 links.
- 1926 U.S. General Land Office dependent resurvey reestablished this corner by record measurements from the north and west, which checks with Tamarack swamp call by original notes. Corner to the east was not used. No evidence of the original corner was found. An iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 12" Poplar N 35-30 E 19 links, 5" Spruce S 77-45 E 34 links, 14" Poplar S 63 W 27 links, and 4" Balsam N 48 W 3 links.
- 1980 U.S. Forest Service technician G. Brama found the corner monumented with a GLO brass cap monument in good condition up 12". The following bearing trees were found: Rotted Poplar stump at N 36 E 12.5' and Rotted Spruce stump at S 77 E 22.4'. No evidence was found of the other two trees. Four new bearing trees were marked and are shown on this certificate. Steel sign posts were set east and north of the corner.
- 1982 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1982 Analysis of the above data indicates that the location of this Government corner has been perpetuated. I accepted the monument as marking the corner location as when set in 1926 by the GLO resurvey based on bearing tree evidence.