CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
Northwest Corner of Section 30	,Township <u>141 N</u> , Range <u>31 W</u> , <u>5th</u> P.M.
STATE OF MINNESOTA, County of Cass	
At the corner location shown on the sketch:	
On $\frac{8/27/84}{\text{DATE}}$ found a $\frac{12}{2}$ iron pipe	up 8" ,
☐ left monument as found, ☐ lowered monument, ☒ removed monument (explain)	
On $\frac{12/5/84}{\text{DATE}}$ placed a $\frac{2\frac{1}{2}}{\text{inch by }30^{\text{m}}}$ galvanized pipe with a 3 inch brass cap stamped as shown, flush with ground.	
FIELD TO RESERVE SE SE SE	N 38°E, 130.09 ft. to a scribed 8 in. W. Oak with nail on side. IN 17°E, 75.99 ft. to a scribed 12 in. twin W. Oak with nail on side. N 62°E, 74.02 ft to a scribed 14 in. J. Pine with nail on side. N 62°E, 74.02 ft to a scribed 14 in. J. Pine with nail on side. N 62°E, 74.02 ft to a scribed 14 in. J. Pine with nail on side.
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Line	OFFICE OF THE REGISTER OF DEEDS County of
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 280 483

Statement of Evidence:

NORTHWEST CORNER SECTION 30, TOWNSHIP 141 NORTH, RANGE 31 WEST OF THE 5th PRINCIPAL MERIDIAN.

1871 - The original Public Land Survey was run by G. R. Stuntz. A wood post was set to mark the corner and 4 bearing trees were recorded as accessories:

9" Aspen N 80°E 13 links (8.58')
9" Aspen S 65°E 16 links (10.56')
6" W. Pine S 43°W 19 links (12.54')
6""W. Pine N 70°W 10 links (6.60')

1921 - Elmer B. Horst Deputy Casst County Surveyor resurveyed Section 30 he found an 2½ x148 In capped iron monument set by Hubbard County Surveyor sofrom the original bearing trees. Reseast County Record Book C, page 445.

1967 - D.N.R. Engineering found a iron monument inplace set 2 bearing trees.

7" Oak N-NE 52.45 ft. nail and bottle cap Corner Fence Post East 16.52 ft. nail and Bottle cap

1984 - Kerick Surveying, Inc. Bemidji, MN, found 1½ inch iron pipe up 8 inches, no trace of 2½ in. capped monument astrefered to in 1921 survey. Found the two receiver corner accessories from 1967 search, ties check but are in poor condition. After a subdivision of Section 30 there was no doubt that this corner was in the location that the Hubbard County Surveyor perpetuated in 1921. Replaced 1½ in. iron pipe with U.S.F.S. monument and recorded three new accessories that appear on this certificate.