CERTIFICATE OF LOCATION OF GOVERNMENT CORNER Point on East Line 657.29' South of Northeast Corner of Section 36 ,Township 141 N, Range 29 W , 5th P.M.	
STATE OF MINNESOTA, County ofCass	Latitude: 46° 59' 32.237" Longitude: 94° 16' 59.305"
On found a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
☑ On 5/1/89 placed a 2 inch by 48 inch iron pipe with brass cap and prastic base with magnet.	
Magnetic Decl: 5° East SKETCH OF R Not to Scale	EFERENCE TIES All distances are horizontal to nail in side of tree. 9" Red Oak N 12 E 64.10' 6" Ash N 58 E 40.69'
y s 22 w	Monument Stamped T141N 21.33' R29W POL S36\S31 1989
All trees are painted with red enamel and RLS 17008 marked with a 54-3 (bearing tree) tag.	
Statement of evidence relative to this corner location is on back of page. $3/2364$	
I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota. David S. Landecker Date 5-24-66 Registration No. 17008	OFFICE OF THE COUNTY RECORDER County of

Statement of Evidence:

• . . •

Point On East Line Section 36, Township 141 North, Range 29 West, Cass County, Minnesota

> VW-25 141-29 Bk.13 Pg.43

1873 P.H. Conger, U.S. Deputy Surveyor, ran the East line of Township 141 North, Range 29 West. During that survey, the Northeast corner, East Quarter corner and Southeast corner of Section 36 were set, according to the plat and survey notes.

The East Quarter corner now falls in the lake and is therefore unsetable.

1955 John Howard surveyed the plat of JOHNSON'S BEACH. His plat indicates the section line is a straight line between the Northwest and Southwest section corners. Our examination of this plat, however, identifies an inconsistency in the plat and existing monumentation. Therefor, because of the numerous mathematical differences between the existing found monumentation and plat notations, the plat line was not used as the basis for determining the location of the east line of Section 36.

1986 Roger Mustonen, Licensed Land Surveyor Number 11945, surveys the plat of OTTER BAY ESTATES. East line of plat is identified as section line and is monumented same. The plat monumentation, as found and analyzed as of May 1, 1989, was not accepted as being on the section line.

1989 on May 1 a Landecker-Stevenson & Associates crew set a Point on Line 657.29 feet Southerly of the Northeast corner of Section 36 between the recovered Northeast and Southeast corners of said Section 36. A 2 inch by 48 inch iron pipe with brass cap and plastic base with magnet was set. Bearing trees were marked as shown and a steel sign post was set as noted on front of this certificate.