| CERTIFICATE OF LOCATION OF GOVERNMENT CORNER  MEANDER CORNER. 1 Corner of Section 13 Township 140, Range 30, 5th P.M.   |   |
|---|---|
|   |   |
| STATE OF MINNESOTA, County ofCASS   |   |
| At the corner location shown on the sketch:   |   |
| ☑ On 8-25-81 found a 2" Inside Dia, Iron Pipe, (up 1.4'), at top of high    DATE   lake bank pipe is leaning ± 0.3' North.     ☑ left monument as found, □ lowered monument, □ removed monument (explain) |   |
| ☐ On placed a   |   |
| Onplaced a  |   |
| SKETCH OF REFERENCE TIES  |   |
| 1,  |   |
| .WEBB LAKE  |   |
|   |   |
|   |   |
| 24'   |   |
| Noil & Disc<br>NW side  |   |
| Nail 8 Disc 2" Burr Oak   |   |
| 2" Ash  |   |
| N 750 W 3.80  |   |
| Note: Bearings observed with compass  |   |
| Note: Bearings abserved with compass  |   |
|   | Sw side<br>P.P.   |
| L   |   |
| 82' 1   |   |
|   |   |
| co  | HWY.  |
|   | H W 1.  |
| J.A.G.  |   |
| Statement of evidence relative to this corner location is on back of page. FILE: A - 338  |   |
| I hereby certify that this document and the data contained herein was prepared by me or under   | OFFICE OF THE REGISTER OF DEEDS  County of                                  |
| my direct supervision.  | I hereby certify that this document was filed in                            |
| 00-8-11 Galocu Chaloc   | the Reg. of Deeds office at 2:10 PM. on the  14 day of November A.D., 19 90 |
| Registration No. 16098  | Register of Deeds Planding Konglin  |
| প্র Land Surveyor, 🗆 Professional Engineer  | By,Deputy   |
| ☐ County Surveyor, ☐ County Engineer  | DOCUMENT NO. 324963   |

## Meander Corner #1, Section 13, Township 140 North, Rance 30 West

- The following offices were contacted for information on this corner:
  Minnesota Secretary of State
  Cass County Recorder
  Cass County Surveyor
- 1865 The US General Land Office field notes state that they set a post and measured to the following bearing trees: 10" Aspen S 63 W, 33.66' and an 8" Birch S 46-30 E, 22.44'.
- 1916 In Book C, page 227, survey record 426, in January 1916, E.B. Horst searched for this meander corner but could not find it due to deep snow.
- 1959 In July, W. Spain surveyed a plat in Govt Lot 4, Section 18. His plat shows an iron monument at the meander corner. No further description or procedures are available.
- 1959 In August, the DNR Bureau of Engineering located an iron pipe with the help of W. Spain and accepted it as the meander corner
- 1981 In August, the DNR again searched for and found a 2" inside diameter iron pipe and accepted it as the meander corner.