| CERTIFICATE OF LOCATION OF GOVERNMENT CORNER | |
|---|--|
| North Quarter Corner of Section 34 , Township 143 , Range 25 , 5th P.M. | |
| STATE OF MINNESOTA, County of | |
| At the corner location shown on the sketch: | |
| | |
| On 10/26/90 found a 2½ inch aluminum capped monument 8 inches | |
| above ground. ☑ left monument as found, □ lowered manument, □ removed manument (explain) | |
| | |
| Onplaced a | |
| Magnetic Docl. 5° Fast SKETCH OF REFERENCE TIES All distances are | |
| Magnetic Decl: 5° East SKETCH OF RE | HERENCE HES All distances are horizontal to nail |
| 1 4 | in side of tree |
| (1983 BT) 8" Birch | |
| N 50 W 41.07' | |
| 6" Poplar | |
| \sim | N 15 E 27.95' |
| | |
| | / |
| | / |
| | |
| 10" Birch S 82 W 23.25' | |
| S 82 W 23.25 W | |
| 6" E | Basswood & |
| Monument is located on top S 60 of bank, 15' from crest, | DE 27.44' Monument Stamped |
| 25' from edge of Sugar Lake. | Dept. of the Interior ··· Do Not Disturb |
| 8' steel sign post 3.15' West. | T143N R25W |
| All trees are painted with red enam | nel and $\frac{S27}{\sqrt{534}}$ |
| marked with a 54-3 (Bearing Tree) t | ag. 1983 |
| | Cadastral Survey Bur. of Land Management |
| | bur. Or Land Management |
| Statement of evidence relative to this corner location is on back of page. | |
| 32.5279 | |
| I hereby certify that this document and the data | OFFICE OF THE REGISTER OF DEEDS |
| contained herein was prepared by me or under | County of |
| my direct supervision. | |
| Muy of A dila 11/28/90 | the Reg. of Deeds office at 410 l. M. on the 29 day of Machine A.D., 19 20 |
| Registration No17008 | Register of Deeds Clantine Kaylon |
| 🖾 Land Surveyor, 🗆 Professional Engineer | By M, Deputy |
| ☐ County Surveyor, ☐ County Engineer | DOCUMENT NO. 325279 |

V-15

1872 Hayward and Griffin, U.S. Deputy Surveyors, originally established this corner position while subdividing Township 143 North, Range 25 West. The notes indicate a wood post was set to mark the corner position and the following witnesses: a 14 inch Cedar North 50 degrees East a distance of 6 links; and a 10 inch Birch South 60 and 1/2 degrees West a distance of 10 links.

1976 Bureau of Land Management dependent resurvey reestablished this corner proportionally. A 2 and 1/2 inch by 28 inch aluminum pipe with an aluminum cap was set to mark the corner. The following bearing trees were marked: a 10 inch Aspen South 2 degrees West a distance of 21 links (13.86 feet); and a 5 inch Balsam North 43 degrees West a distance of 11 and 1/2 links (7.59 feet).

1979 Gary Stevenson & Associates, Inc., survey crew found the 1976 Bureau of Land Management monuments around Section 34, Township 143 North, Range 25 West. They were used to subdivide said section. 1983 Mr. Stevenson alerted the Bureau of Land Management to information from a 1900 U.S. Corps of Engineers survey which could affect the Bureau of Land Management's 1976 survey in the township.

1983 Bureau of Land Management performed a corrective dependent resurvey based on Mr. Stevenson's 1983 notification. They removed and destroyed the corner and accessories marked in the 1976 Bureau of Land Management survey. A new 2 and 1/2 inch by 28 inch aluminum pipe with stamped brass cap was set to mark the corner. The following bearing trees were marked: a 10 inch Aspen South 45 degrees East a distance of 24 links (15.84 feet); and a 6 inch Birch North 43 degrees West a distance of 62 links (40.92 feet). The corners whereby this corner was proportioned from (the north) were reset due to the U.S. Corps of Engineers information that led to the recovery of original corners to the north and east of this section. Therefore, this corner was reset at the proportional position using this new information.

1990 on October 26, a Landecker & Associates, Inc., survey crew found the 2 and 1/2 inch aluminum capped monument 8 inches above ground as set by the Bureau of Land Management in 1983. Bearing trees are marked as shown and a steel sign post was set as noted on front of this certificate.