CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Statement of Evidence:

North Quarter Corner, Section 18, T.140 N., R.31 W., 5th P.M.

AMI SURVEYORS & MAPPERS contacted the following for survey information:

Cass County Surveyor's Office, Walker, MN
Terry Freeman, RLS with Landecker & Associates, Walker MN
Lowell Schellack, RLS with SCHELLACK ENG/SURVEY, Park Rapids, MN
John D. Walker, RLS with MN DNR, Brainerd, MN
Michael Hayes, RLS with U.S. Forest Service, Cass Lake, MN
Milo Stefan, RLS with Stefan Surveying, Remer, MN
Walter E. Curo, former RLS, Hackensack, MN

- Corner established by U.S. General Land Office survey and marked with a post.

 From which: W Pine 20" S 40 E 10 links (6.60 ft)

 W Pine 20" N 35 W 36 links (23.76 ft)
- January 20, Curo Surveying Certificate of Survey for Part of Government Lots 1 & 2, Section 18-140-31 shows north line of Section 18, but no ties to the north quarter corner. (During the fall of 2002, Walter E. Curo states that they did not find any evidence of the original GLO corner or original bearing trees.)
- July 17, Landecker & Associates Certificate of Survey for Part of Government Lot 3, Section 18-140-31 shows north line of Government Lot 3, but no ties to the north quarter corner. (5/7/02 Terry Freeman, RLS states his crew found a 3" iron pipe in the vicinity of trail intersections S, E & WNW.)
- August 08, Schellack Engineering & Land Surveying Certificate of Survey for part of Government Lot 3, Section 18-140-31 shows the north quarter corner marked by a 3" iron pipe found in place. (April 16, 2002 Lowell Schellack, RLS states "the north quarter corner of Section 18 is a 3" diameter iron pipe, up 1 foot".)
- June 26, AMI Surveyors & Mappers locate 3" diameter iron pipe in the vicinity of the north quarter corner, and searched for evidence of the original GLO post and bearing trees.
- November 12, Roger Mustonen, RLS and Milo Stefan, RLS visit the site to investigate further, and make a thorough and meticulous search for evidence of the ordinal GLO corner, but found none.
- December 07, The notable absence of evidence of the original GLO corner post & bearing trees at this site would seem to favor the presumption that they were never properly established. Set a 1" iron pipe at prorated lost position.

Cass/North99 Coordinates are: Northing 153142.017 Easting 392099.185

Page 2 of 2 Pages