

A000609631

OFFICE OF THE COUNTY RECORDER CASS COUNTY, MINNESOTA CERTIFIED, FILED, AND/OR RECORDED ON

2/18/2015 10:17:32 AM AS DOC #: A000609631

PAGES: 2 REC FEES: 0.00

KATHRYN M. NORBY CASS COUNTY RECORDER

BY SR Dep TX#: 121093

Twp 135 Rge 30 Index No. A.0-05.0 CERTIFICATE OF LOCATION OF GOVERNMENT CORNER ,Range 30 W. , 5th P.M. Northeast Corner of Section 6, Township 135 N. State of Minnesota, County of Cass At the corner location shown on the sketch: On Nov.4, 2014 found 1/2" Capped iron pipe with a broken cap 0.5' below surface ☐ removed monument (explain) ✓ left monument as found ☐ lowered monument On _ placed SKETCH OF REFERENCE TIES 10" Birch Found Nail SW NOT TO SCALE 12" Ash Set Nail SE Woods /Broken Cap 0.5ft Under 72ND ST SW Surface Woods NOTE: All bearings are true. 10" Spruce Coordinates are Cass Woods Set Nail NE CO. South NAD 83 96 ADJ N=241248.200 E=492214.623 Statement of evidence relative to this corner location is on the back of this page. I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly

Licensed Land Surveyor under the laws

Date 2-1-15 MN License No. 40827

Daniek W. Skinner, Land Surveyor

of the State of Minnesota.



Page 2 of 2 A000609631

Index No. A.0-05.0

Statement of Evidence

Northeast Corner Section 6, Township 135 North, Range 30 West

1858 Original US General Land Office Survey by E.N. Darling, set a wood post and bearing trees as noted:

6" Tamarack	N 20° W	22 links
6" Tamarack	S 41°E	14 links
6" Spruce	N 2° E	19 links
5" Fir	S 35° W	16 links

Information on file with the Minnesota Historical Society in St. Paul, MN and copies are filed with the CCHD/SO.

1914 Cass County Survey Record Book "B" P. 57-61 and Curo book 094, page 126-127, F.A. Donner set iron pipe at corner from existing bearing trees. The following additional bearing trees were established at this time:

Information on file with CCHD/SO.

2002 David Landecker, RLS 17008, Certification of Survey shows monument found. Information on file with CCHD/SO.

2014 Karvakko Engineering found a ½ in iron pipe with a broken cap .5 ft below road surface and accepted it as the corner.

Reference ties: