


T. 134 R. 30 M. 5TH Coordinates: X _____ Y _____
E11421 Corner common to sections 21, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1868

Original monument POST

Bearing Trees	
Species <u>R. OAK</u>	<u>R. OAK</u>
Diameter <u>9"</u>	<u>9"</u>
Bearing <u>NORTH</u>	<u>N17W</u>
Distance <u>46 LKS.</u>	<u>49 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1987 By Dave Landecker

Corner Certificate - Doc # 302263

Set 2" sq x 36" iron w/ aluminum cap at proportional position

Bearing Trees, Reference Objects

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Bearing Trees, Reference Objects

<u>Red oak</u>	<u>Red oak</u>	<u>Red oak</u>	<u>Red oak</u>
<u>5"</u>	<u>6"</u>	<u>8"</u>	<u>12"</u>
<u>S55E</u>	<u>S5W</u>	<u>S72W</u>	<u>N18W</u>
<u>17.6'</u>	<u>36.24'</u>	<u>50.41'</u>	<u>16.77'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Dave Landecker - 1987

Doc. # 302263