


Index No. C 1

CASS COUNTY LAND CORNER RECORD

T. 134 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
W/4 6 Corner common to sections 6 AND 1-134-33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>SP. PINE</u>	<u>SP. PINE</u>
Diameter <u>10"</u>	<u>10"</u>
Bearing <u>S76W</u>	<u>N26W</u>
Distance <u>10 LKS</u>	<u>24 LKS.</u>

Original Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 11/20/90 By Thomas Thiessen  
Location filed Cert. Filed Doc. # 343239  
Monument Found 3/8" iron pin down 0.8'  
3-22-92 set 1/2" iron pipe monument capped  
RLS No. 16097 in E Co. Rd. # 30.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species <u>OAK</u>	<u>POWER POLE</u>	<u>POWER POLE</u>	<u>RR tie</u>
Diameter <u>6"</u>	_____	_____	<u>Fence Post</u>
Bearing <u>NW</u>	<u>NW</u>	<u>SW</u>	<u>SW</u>
Distance <u>115.28'</u>	<u>150.68'</u>	<u>172.41'</u>	<u>76.23'</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
11-24-92 Cert. Filed by Thomas Thiessen,  
RLS 16097, Doc # 343239.

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_