


T. 137 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 7 Corner common to sections 5, 6, 7, 8 W.C. 25 LKS SOUTH



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument W.C. Post

| Species | Bearing | Trees | Distance |
|-----------------|-----------------|----------------|----------------|
| <u>ELM</u> | <u>N. PINE</u> | <u>ELM</u> | <u>ELM</u> |
| <u>8"</u> | <u>10"</u> | <u>7"</u> | <u>5"</u> |
| <u>N58E</u> | <u>S70W</u> | <u>N34W</u> | <u>S63E</u> |
| <u>150 LKS.</u> | <u>252 LKS.</u> | <u>215 LKS</u> | <u>100 LKS</u> |

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN Curo

Location filed COUNTY RESURVEY 'E-22'

Monument 2'14" x 48" I.M. W.C.'S 135.7' WEST AND 210' NORTH

1915, Curo, Book C' P. 494 AND WOOD POST SET IN RIVER AND BITS: 10" N. PINE N8-23E 113.32', 24" ELM S62E 98.85', 8" POPLAR NO-42 W 203.5'

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|----------------|-------------|----------------|----------------|
| <u>N. PINE</u> | <u>10"</u> | <u>N81-23E</u> | <u>113.32'</u> |
| <u>ELM</u> | <u>24"</u> | <u>S62E</u> | <u>98.85'</u> |
| <u>POPLAR</u> | <u>8"</u> | <u>N0-42W</u> | <u>203.5'</u> |
| <u>I.M.</u> | <u>W.C.</u> | <u>NORTH</u> | <u>210'</u> |

Evidence of Subsequent Corner Restoration

Year of search 1915 By JOHN Curo

COUNTY BOOK 'C' P 496. SET 194 X 9' GALV. IRON, W/ A 2' x 48" GALV. CAPPED IRON OVER IT. 1915, Curo, Book C' P 521 NEW BITS (Below)

1915 - J. A. Johnston - microfilm - roll 115 BX 89 P. 66-70 P. 79 set W.C. N. 210.0' & W. 135.7' I.M.

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|----------------|-------------|----------------|----------------|
| <u>N. PINE</u> | <u>10"</u> | <u>N81-23E</u> | <u>113.32'</u> |
| <u>ELM</u> | <u>24"</u> | <u>S62E</u> | <u>98.85'</u> |
| <u>POPLAR</u> | <u>8"</u> | <u>N0-42W</u> | <u>203.5'</u> |
| <u>I.M.</u> | <u>W.C.</u> | <u>NORTH</u> | <u>210'</u> |

E-5

Subsequent Corner Restoration

Year surveyed 1999 By Landecker 17008

Location filed CCSO

Monument Certificate of survey indicates corner position in Norway Brook.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____