


Index No. ES

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 7 Corner common to sections 5, 6, 7, 8



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

		Bearing Trees	
Species	<u>W. PINE</u>	<u>W. PINE</u>	_____
Diameter	<u>20"</u>	<u>24"</u>	_____
Bearing	<u>N12E</u>	<u>S60E</u>	_____
Distance	<u>214 LKS</u>	<u>237 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1936? By CCC  
Location filed Washburn Lake - BK# 3 P. 38  
Monument End iron pipe section corner - brushed  
line W.  
Tip on E-W brushed line 21 ch. South

Evidence of Subsequent Corner Restoration

Year of search 1983 By DNR-Engineering  
Map notes in file  
End 1 3/4" lip  
River is 310' West

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Elm</u>	<u>Oak</u>	<u>Elm</u>
<u>7"</u>	<u>14"</u>	<u>6"</u>
<u>60°</u>	<u>98°</u>	<u>136°</u>
<u>92.25'</u>	<u>80.10'</u>	<u>58.67'</u>

w/ yellow tag

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_