


T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 4 Corner common to sections 3, 4 AND 33, 34 - 140 - 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument POST

	Bearing	Trees		
Species	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>
Diameter	<u>5"</u>	<u>6"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>N59E</u>	<u>S34E</u>	<u>S48W</u>	<u>N65W</u>
Distance	<u>18 LKS</u>	<u>34 LKS</u>	<u>25 LKS</u>	<u>13 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed 1911 By JOHN CURO

Location filed COUNTY SURVEY RECORD BOOK "A" P364-368

Monument END STAKE SET BY CURO SET 8X8X36"
CONCRETE POST

1919 END CONCRETE POST IN ROAD

1922 COUNTY RESURVEY "E9"

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration

Year of search 1938 By CCC

Washburn Lake - BK# 13 P. 6

at 5230' from E. intersection with road S -
Set approx cor 6" Tam squared on 3 sides

Dec. 1918, Trip road order shows no survey

Bearing Trees, Reference Objects

A-13

Subsequent Corner Restoration

Year surveyed 1979 By Cathie Dept

Location filed CRATE # 47

Monument Rib. spike in place. 1980 SET 2" I.P.

TICS 8" Round NW 119.65
20' wire SE? 129.8'

1911 - Hurry Todd - microfilm - roll 115 BK 73
P. 35-36

End corner set by Curo under culvert
Set 8X8 X36" cement post.

1999 - CCSO found 2" I.P. down 1.4'
on E. Co. Rd. 47, 11' W of Co. Rd. 56.

witnessed as follows:

Tele. Pole Post, N59°W, 109.54' *

P. Pole, N53°E, 66.99 *

19" W. Pine, S60°E, 129.76 @

St Sign Post, S70°W, 36.47 (N Plange)

* denotes double head spike
@ denotes double head spk with brass washer

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Corner GPS CCSO 8/1/02

CCSO fd. spike w/washer, down 0.2,
on E #47, 13' ± W. of E Co. Rd. #174
