


T. 140 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 27 Corner common to sections 22, 23, 26, 27



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1873  
 Original monument Post

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Species	Bearing		Trees	
	TAM	TAM	TAM	N. PINE
Diameter	4"	4"	4"	10"
Bearing	N45E	N24-15W	S36W	S55-45E
Distance	18 LKS	113 LKS	74 LKS	662 LKS

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1938 By CCC  
 Location filed Washburn Lake - R.R. # 6 P. 68  
 Monument at 5324' from E. End of d. ex. cor -  
4" Spruce squared on 4 sides 5' above ground  
71' South of line

Evidence of Subsequent Corner Restoration  
 Year of search 1957 By DNR - Engineering  
Map and notes in file  
Found 4" I.P. in place - capped & marked

Bearing Trees, Reference Objects  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1912 By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument Co DITCH SURVEY BK 28 BOX 2  
OF Co DITCH SURVEY BOOKS, PG 6

R-17

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
1991 Cert. Filed by David Landsker  
Doc # 329222  
found 2 1/2" iron pipe up 16" in Tamarack  
bag with 3" x 5" oblong cast iron cap. Ties:  
5" Tamarack N4E 92.35'; 5" Tamarack  
N74E 42.34'; 5" Tamarack S66E 81.09'