


T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
E 1/4 26 Corner common to sections 25, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>W. BIRCH</u>	<u>W. BIRCH</u>	
Diameter <u>5"</u>	<u>6"</u>	
Bearing <u>S80E</u>	<u>N65W</u>	
Distance <u>30 LKS</u>	<u>23 LKS</u>	

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
 Location filed SECRETARY OF STATE
 Monument PROPORTIONAL POSITION - NO ORIG EVIDENCE - SET
1x36" i.p. w/BRASS CAP
1/4
526/525
1918

Evidence of Subsequent Corner Restoration

Year of search 1922 By J.H. ELYAN
COUNTY BOOK "D" P. 75 FIND 600' 120' CORNER

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
<u>N. PINE</u>	<u>SAPRLE</u>	
Diameter <u>10"</u>	<u>10"</u>	
Bearing <u>N17 3/4 E</u>	<u>N18 3/4 W</u>	
Distance <u>208 LKS</u>	<u>207 LKS</u>	

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

T-21

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILLOCKERMAN - 1971
1989 Certificate - Bill Osulfsen, RLS 17767
Doc. #310943
1989 Certificate - David Landecker
Doc. #312361
Found GLO 1" iron monument with brass
cap. Ties: 27" Norway Pine N18E 136.90';
6" Maple N26 W 52.73'; 9" Burr Oak
S 5 1/2 W 45.57'.
1999 - Landecker & Assoc. - Survey info
indicates BC in place.
Feb. 2005 T. Freeman #21367
Cert. of Survey shows monument found.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____