


T. 141 R. 28 M. 5TH Coordinates: X _____ Y _____
N 74 35 Corner common to sections 26, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species TAM. TAM.
Diameter 15" 8"
Bearing S74W N60E
Distance 30 LKS 33 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed SECRETARY OF STATE
Monument Iron DELAYED WOOD STAKE AND BRASS CAP B.T.S: CEDAR
TAM 30" 538 1/2 W 30 LKS, TAM (DOWN) 10" N 61 E 33 LKS
SET 1x36" I.P. W/BRASS CAP. 1/4 526
535

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species TAM CEDAR
Diameter 15" 8"
Bearing S18 1/4 W N49 3/4 W
Distance 72 LKS. 56 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - MANDERS SUNSET VIEW
JOHN E. HOWARD 1955

1989 Certificate - William Osulfen
Doc. # 310945

1989 Certificate - David Landecker
Doc. # 312352

Found 1" iron monument with brass cap.
TIES: 11" Cedar S 55 W 51.94'; 10" Cedar
N 49 W 36.96'; 7" Tamarack N 82 E
42.83'; 7" Cedar S 5 E 32.19'.