


Index No. D 5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X 458001.46 Y 191842.73

MC Corner common to sections 5, 6  
AND 5 1/2



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1x36" 1/2" w/ brass cap  
Species BIRCH Bearing BIRCH Trees 1918  
Diameter 8"  
Bearing S17-30E S64W  
Distance 43 LKS 41 LKS

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1977 By Unknown  
Location filed \_\_\_\_\_  
Monument GLO monument washed down bank in rain storm.

Evidence of Subsequent Corner Restoration

Year of search 11/03 By NLSEM  
Found GLO midway down steep bank, set 2 1/2" pipe w/ brass cap as witness 10.44 S. of calculated position. A.C. of L was filed.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Balsam	Basswood	Maple	GLO
<u>5 1/2"</u>	<u>9 1/2"</u>	<u>11"</u>	<u>Mon.</u>
<u>S53°W</u>	<u>S16°E</u>	<u>S52°E</u>	<u>N24°W</u>
<u>14.32'</u>	<u>20.97'</u>	<u>9.97'</u>	<u>26.25'</u>

D-5

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument Aug 2003 M. Landerer #7452  
Certs. of Srg. shows Mon. found

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared #480065  
Filed at CCRO

By #16089  
Date 2/12/04