


Index No. V 11

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
N 1/4 33 Corner common to sections 28, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument Post

Species	Bearing	Trees
<u>ASPEN</u>	<u>B"</u>	<u>BIRCH</u>
<u>B"</u>	<u>S28E</u>	<u>B"</u>
<u>B"</u>	<u>81KS</u>	<u>71KS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1963 By BILL OKERMAN

Location filed CORNER CERTIFICATE (NO. 367)

Monument END 1 1/2" I.P. - NOTES OF C.J. WHITE CO. ENGINEER
1926 - GRANT - BOOK D P176 - POINT AT 565' EAST
OF CORNER

Species	Bearing	Trees, Reference Objects
<u>TAM.</u>	<u>9"</u>	<u>BR. OAK CEDAR POST</u>
<u>9"</u>	<u>571W</u>	<u>5" 574E EAST</u>
<u>9"</u>	<u>92.3'</u>	<u>15.8' 3.3'</u>

1963 TIES

Evidence of Subsequent Corner Restoration

Year of search 1961 By DNR-Engineering

Map notes in file

Found 2" I.P. in place

Bearing Trees, Reference Objects

V-11

Subsequent Corner Restoration V 11

Year surveyed 1921 By _____

Location filed _____

Monument Co DITCH SURVEY BK 6 BOX 2 OF
Co DITCH SURVEY BOOKS, PG 9-10-11

JULY 1999 MIKE WAHMAN CASS LAND DEPT,
FA MONUMENT IN GOOD CONDITION, 50'
OFF RAILROAD, BURR OAK GOOD CONDITION,
DID NOT CHECK TAMARAC

CORNER GPS 4/4/03 CCSO

CCSO 4/4/03 Found brass cap conc.
Cyl., up 2.2', 160' ± S. of 1/4 Co. Rd. #4

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Bill Okerman 1963 - recorded 1965

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____