

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 33 Corner common to sections 27, 28, 33, 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	Distance
<u>W. PINE</u>	<u>W. PINE</u>	<u>BIRCH</u>	<u>W. PINE</u>
<u>14"</u>	<u>28"</u>	<u>14"</u>	<u>16"</u>
<u>S45W</u>	<u>N39E</u>	<u>N50W</u>	<u>S55W</u>
<u>10 LKS</u>	<u>60 LKS</u>	<u>47 LKS</u>	<u>42 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1940 By R.T. DEBANT
Location filed CCC NOTES
Monument L.P. ON 4" OAK. S. SIDE SOUTH 60 TO CORNER
1973 - KRAUSE - USFS. FND 1 1/2" I.P. SOUTH OF HWY.
ON TOP OF BACK SLOPE
1986 - G. HWY DEPT - FND 2" I.P. 55' SOUTH OF P.I. OF RD.

Evidence of Subsequent Corner Restoration

Year of search 1982 By G. HWY & SURVEYOR
FND IRON AT P.I. OF CURVE AND ALSO IRON ON
TOP OF OAK SLOPE SOUTH OF RD. PIPE AT P.I. IN
ROAD IS ROGER MUSTONEN'S - HE FND PIPE IN RD -
INFO FROM BILL SPAIN. RESET PIPE AT ROAD SURFACE.
MUSTONEN FND A PIPE DOWN 3'

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

V-13

Subsequent Corner Restoration

Year surveyed 1961 By DNRE Engineering
Location filed Map notes in file
Monument Fnd 2" I.P. in place
1973 - Krause, USFS
CORNER GPS 4/4/03 CCSO
CCSO 4/4/03 Fd. brass cap MSFS man.
Flush, 4' ± S. of 2 co. Ad. #4.
1986 witnesses are good

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Walt Curo - 1986
Doc. # 291468
Fnd 2" I.P. down 2.3' in Road set
2" x 24" galv. I.P. w/ brass cap.
7" W. oak N35°W 77.14'
8" Balsam N27°E 76.26'
4" Twin Maple S25°E 56.29'
8" Maple S25°W 62.12'

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____