


T. 142 R. 28 M. 5th Coordinates: X _____ Y _____

NE 2 Corner common to sections 1, 2 and 35,36-143-28



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search 1916 by Baldwin
Monument found corner
Survey Rec #287, Bk B, pg 216

Bearing Trees

Species	Birch	Birch	Birch	Spruce
Diameter	12"	8"	6"	5"
Bearing	N 66° E	N 64° W	S 20° W	S 64° E
Distance	7 links	13 links	16 links	10 links

Original Bearing Trees Found

Species	Birch	Birch	Spruce
Diameter	12"	6"	5"
Bearing	N 81° E	S 61° W	S 59° E
Distance	20.50'	36.30'	35.70'

Subsequent Corner Restoration

Year surveyed 5/1916 By H.F. Baldwin, Deputy Surveyor
Location filed: Survey Record #287 Book B, page 217 and Curo
Monument: Set Iron Monument
Curo Book 55, page 18, set from GLO witness trees.

Evidence of Subsequent Corner Restoration

Year of search 5/1916 By H.F. Baldwin, Deputy Surveyor
Location filed: Survey Record No. 288, Book B, page 226 and Curo
Monument: Set Iron Monument
Curo Book 77, page 17, trees are gone, but the corner post has been established by a later survey, accepted by the natives as correct, since this country was opened for homestead entry.

Bearing Trees, Reference Objects

Species			
Diameter			
Bearing			
Distance			

Bearing Trees, Reference Objects

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 8/1919 By E.B. Horst, LS 376
Location filed: Survey Record No. 435, Book C, page 342
Monument: I.M.

Evidence of Subsequent Corner Restoration Found

Year of search 9/2002 By CCHD/SO
Location filed: #2000.031
Monument: found a 1/2 inch iron pipe down 1.0', 2'+,-, S. of centerline of Co. Rd. #172 and 2'+,-, E. of centerline of Co. Rd. #157 and the 1993 USFS witnesses.

6/1928, E.G. Harrington, U.S. Cadastral Engineer
Minnesota Historical Society
The field notes of part of Harrington's work were lost. The accepted point for corner is marked by 2" galv. iron pipe, with cap flush, set by Co. Surveyor, no new iron post is set. No accessories available.

7/2009, CCHD/SO
#2009.025
Found USFS brass capped iron pipe, down 2.1', 4'+,- S of centerline Co. Rd. 172, on centerline extension of Co. Rd. 157. USFS 1993 witnesses all good.

12/1933, Boy Lake Township
Final Road Order of Town Board
Surveyor's Report and plat indicates road on the N. and E. lines of Sec. 2, No survey made as road follows section line.


8/2019, CCHD/SO
#2009.025
Found mag nail, 1.5'+,- S of centerline Co. Rd. #172, 2'+,-, E. of centerline Co. Rd. #157. USFS 1993 witnesses all good.

7/1993, C. Krause and R. Main, technicians, USFS
USFS, Book 6, page 14 T143N R28W
Fd. 2 1/2" x 36" county iron pipe - top near S35 | S36
surface of road, bent slightly N. top 12" & cap S2 | S1
gone, in place of co. iron pipe, set 2" x 24" iron T142N
pipe with brass cap, down 12", and witnessed. 1993
8" W. Oak, N 36° E, 90.48' USFS
Power Pole, N 30° W, 65.58'
Steel Sign Post, S 51° E, 80.90'
Steel Sign Post, S 45° W, 81.95'

Index No. A 21

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 571 Coordinates: X _____ Y _____
NE 2 Corner common to sections 1, 2 AND 35, 36-143-28



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1873
Original monument POST

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	BIRCH	BIRCH	BIRCH	SPRUCE
Diameter	12"	8"	6"	5"
Bearing	N66E	N64W	S20W	S64E
Distance	7 LKS	13 LKS	16 LKS	10 LKS

Original Bearing Trees Found	
Species	Diameter
_____	_____
_____	_____
_____	_____
_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1916 By JOHN CUPP
Location filed COUNTY SURVEY RECORD BOOK 'B' P. 214-219
Monument FIND OLD ORIG CORNER SET IRON MONUMENT
1919, E.B. HARST, COUNTY BOOK 'C' P. 342 FIND I.M.
1916 - H.F. Baldwin - microfilm - roll 105 BK 55 P. 6
End corner: 3 orig BTS - Badly out of place:

Year of search 1928 By GLD
FIND 2" IP. W/ CAP SET BY COUNTY SURVEYOR
1916 - also on microfilm - roll 115 BK 77 P. 17
P. 41 set I.M.

Bearing Trees, Reference Objects

Species	Bearing Trees			Reference Objects
	Birch	Birch	Spruce	
Diameter	12"	6"	5"	on microfilm
Bearing	N81E	S61W	S59E	set I.M.
Distance	20.5	36.3'	35.7'	

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects	
Species	Diameter
_____	_____
_____	_____
_____	_____
_____	_____

orig BTS Found in 1916 - Baldwin

NO BTS. AVAILABLE

A-21

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed 1/2001 By CCSO
Location filed file # 2001.013
Monument Found 3/4" IP, down 0.3', 4' S.
of & CR # 172 and 2' E W. of & CR # 157.
Witnesses as follows:

Year of search _____ By _____

- 8" W Oak N36°E, 90.48' 60d spk (1993)
- P. Pole N30°W, 65.58' 60d spk (1993)
- Sign Post S45°W, 81.95' (survey Mon. sign)
- Sign Post S51°E, 80.90' (survey Mon. sign)

Dec. 1933, Twp rd order shows no survey

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____