


Index No. A1

CASS COUNTY LAND CORNER RECORD



T. 142 R. 31 M. 5th Coordinates: X _____ Y _____
NW 6 Corner common to sections 6 AND 31-143-31

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
 Original monument POST

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Bearing Trees

Species	Tam	Tam	Tam	Tam
Diameter	8	8	8	7
Bearing	S 40E	N 75E	N 43W	S 72W
Distance	35 lks	19 lks	45 lks	36 lks

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By GLO
 Location filed Sec. of State
 Monument End 2 1/2" Galv. I.P. T143N
also find remains of 4 1/4" Galv. I.P.S R32W S36/S31 R31W
Set 3x30" I.P.W/Dress Cap N 1/4 E. side S1/S6
2 1/2" Iron T142N
1919

Evidence of Subsequent Corner Restoration

Year of search 1915 By Molyneux
micro film-roll 115 BK 81 P. 26
End corner P. 36 set I.M. on top
of 6' tam piling

Bearing Trees, Reference Objects

Species	<u>W. Pine</u>	<u>w. oak</u>	<u>Aspen</u>
Diameter	<u>8"</u>	<u>8"</u>	<u>4"</u>
Bearing	<u>N 38 1/2 E</u>	<u>S 14 1/2 W</u>	<u>N 27 1/2 W</u>
Distance	<u>450 lks</u>	<u>519 lks</u>	<u>407 lks</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1991 Certificate - David Landecker
Doc # 32724
Found 1919 GLO monument in good
condition. Ties: 7" Tamarack N 49 W
40.95'; 5" Tamarack S 69 W 19.70'; 24"
Burr Oak S 14 W 342.50' (1919 BT)

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____