


T. 142 R. 31 M. 5th Coordinates: X _____ Y _____
MC# 4 Corner common to sections 24 & 19, 142-30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	Bearing	Distance
<u>W. Oak</u>	<u>W. Oak</u>	
<u>5"</u>	<u>6"</u>	
<u>S49E</u>	<u>S35W</u>	
<u>19 lks</u>	<u>27 lks.</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By GLO
Location filed _____
Monument Set 1"x36" I.P. w/ Br. Cap for W.C.
0.26 chains south of true as determined
from Original B.S. 12" W. Oak S35W 27 lks and
8" W. Oak (fallen) S49E 19 lks.

Evidence of Subsequent Corner Restoration

Year of search 1986 By Robert Murray
Corner Certificate - Doc # 296970
Find GLO brass cap up 0.5'
5" sign post NE 4'

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. Oak</u>	<u>W. Oak</u>	
<u>5</u>	<u>10</u>	
<u>S72 1/2 E</u>	<u>S 68 3/4 W</u>	
<u>96 lks</u>	<u>64 lks</u>	

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Burr oak</u>	<u>Red oak</u>	<u>Burr oak</u>	
<u>5"</u>	<u>12"</u>	<u>7"</u>	
<u>S82°W</u>	<u>S45°E</u>	<u>N89°E</u>	
<u>31.90'</u>	<u>38.15'</u>	<u>38.92'</u>	

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Robert Murray - 1986