

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____


Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed:
Monument:

Year of search _____ By _____
Location filed:
Monument:

T. 143 R. 26 M. 5th Coordinates: X _____ Y _____
NE 20 Corner common to sections 16, 17, 20, 21



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	
<u>Cedar</u>	<u>Birch</u>	<u>Maple</u>	<u>Birch</u>
Diameter <u>5"</u>	<u>10"</u>	<u>5"</u>	<u>5"</u>
Bearing <u>N54E</u>	<u>S49E</u>	<u>S25W</u>	<u>N59W</u>
Distance <u>15LKS</u>	<u>12LKS</u>	<u>7LKS</u>	<u>20LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed ? By Geo Rappit
Location filed County Survey Record Book B" P98-99
Monument Found old B.T. 5" CEDAR N54E 9'
also on microfilm - roll 115 BK 82 P. 44

Evidence of Subsequent Corner Restoration

Year of search 1922 By GLD
Accepted position for corner at intersection of
roads E-W & S set 2x36" I.P. w/ Brass Cap
W.C. 0.40 CH N. 7143 N R26W
517 | 516
520 | 521

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>CEDAR</u>	<u>8"</u>	<u>S8-30W</u>	<u>71.4'</u>
<u>SPRUCE</u>	<u>10"</u>	<u>S21E</u>	<u>49'</u>
<u>Birch Stump</u>	<u>12"</u>	<u>N18E</u>	<u>44.7'</u>

Bearing Trees, Reference Objects ^{W.C.} 1922

Species	Diameter	Bearing	Distance
<u>Poplar</u>	<u>6"</u>	<u>N74-30E</u>	<u>243LKS</u>
<u>ROCK</u>	<u>4"</u>	<u>S25-30W</u>	<u>212LKS</u>
<u>ROCK</u>	<u>6"</u>	<u>N72-15W</u>	<u>308LKS</u>

Subsequent Corner Restoration

Year surveyed 1959 By DNR-Engineering
Location filed Map's notes in file
Monument Found brass cap monument 33' N of
pit roads and true corner
spike in road
Brass Cap 33' N.
Brace pole NW 55.78'
P.P. SW 48.52'

Evidence of Subsequent Corner Restoration Found ^{11.9}

Year of search _____ By _____
1986 Certificate - Ken Whitshorn
Doc. # 289673
Set 2 1/2" x 30" aluminum pipe with
magnet at base and 3" stamped
aluminum tablet.
Power pole SW 360.55'
9/2" Elm N23W 106.50' (1968 BT)
5" Maple N38W 99.71'

1962? Co. Hwy Dept - Co RD #65
Found corner replace 27.86' S. of W.C. US620
Ties to corner:
Power Pole NW 51.6'
Power Pole SW 51.4'

1925 - Co Hwy Dept - State Rd #4 Corner
ties: US620 W.C. N. 28.0'
Tele. pole SE 46.7'

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____