


T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 31 Corner common to sections 29, 30, 31, 32



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument bst

Bearing Trees

Species	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>
Diameter	<u>5"</u>	<u>4"</u>	<u>6"</u>	<u>7"</u>
Bearing	<u>S8W</u>	<u>S6E</u>	<u>N62W</u>	<u>N6E</u>
Distance	<u>480 LKS</u>	<u>450 LKS</u>	<u>200 LKS</u>	<u>125 LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 1928 By GLO
 Location filed Sec. of State
 Monument Set 2x36" l.p. w/ brass cap T143N R27W
530/529
531/532
1928

Bearing Trees, Reference Objects

Species	<u>NO BITS - Set 4x4" x 6" cedar post</u>
Diameter	<u>along side iron</u>
Bearing	_____
Distance	_____

Evidence of Subsequent Corner Restoration
 Year of search 1986 By Walt Curu
 Corner Certificate - Doc # 291628
in 1970 - USFS found l.p. and cedar post
set sign posts 26' East and 44' west
1986 - found l.p. w/ brass cap, rotted post and both
steel sign posts.

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
Certificate - Walt Curu - 1986
Doc. # 291628
Certificate - William Okerman 1975
Doc. # 223548