


T. 143 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 36 Corner common to sections 25, 36 and 30, 31-143-27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Bearing		Trees	
Species	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>
Diameter	<u>8"</u>	<u>5"</u>	<u>7"</u>
Bearing	<u>N40E</u>	<u>N78W</u>	<u>S30W</u>
Distance	<u>16 LKS</u>	<u>11 LKS</u>	<u>20 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1916 By John Curo

Location filed County Survey Records Book B P. 220-242

Monument Find Old Govt B.T.S.: Dead 8" TAM 54SE
22 LKS, STUMP 5" TAM N78W 11 LKS, STUMP 8" TAM
N40E 16 LKS, STUMP 7" TAM S30W 20 LKS
Set 4x6" CEDAR POST
also on micro film - roll 115 BK 27 P. 47

Bearing Trees, Reference Objects

Species	<u>Dead CEDAR</u>
Diameter	<u>6"</u>
Bearing	<u>N75W</u>
Distance	<u>1.50'</u>

Evidence of Subsequent Corner Restoration

Year of search 1920 By J.H. FLYNN

COUNTY BOOK C P. 340 FND CORNER

1928 - GLO - local corner torn out during road
construction. R.P. Brown showed gov't surveyors location
of old post. Set 2x36" l.p. w/ brass cap T 143N
R28W | R27W

Bearing Trees, Reference Objects

	<u>525</u>	<u>530</u>
Set 4x4x6" HIGH Cedar post	<u>530</u>	<u>531</u>
<u>alongside iron</u>		<u>1928</u>

V-25

Subsequent Corner Restoration

Year surveyed 7/2000 By CCSO

Location filed file # 2000, 031

Monument Set 60d spike w/washer from
witnesses.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1986 Certificate - Walter Curo
Doc. # 291488

Found broken 2" iron pipe 3' below road
surface. Set 2" x 36" galvanized iron
pipe with brass cap over broken
pipe 8" below road surface with RR
spike on top.

Power pole N80W 46.72';
Guy pole N75E 24.79';
6" Balsam N15E 150.46'.