


T. 145 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 34 Corner common to sections 26, 27, 34, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Species	Bearing Trees			
	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>	<u>Cedar</u>
Diameter	<u>8"</u>	<u>6"</u>	<u>6"</u>	<u>5"</u>
Bearing	<u>N20E</u>	<u>S4E</u>	<u>N60W</u>	<u>S85W</u>
Distance	<u>13 LKS</u>	<u>18 LKS</u>	<u>16 LKS</u>	<u>19 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

O = Corner

Subsequent Corner Restoration

Year surveyed 1907 By John Curo
Location filed County Survey Record Book 5 p 323-327
Monument Find Old Govt B.T.S: 8" TAM N20E, 6" TAM, 54 E 18 LKS, 6" TAM N60W 16 LKS, 5" CEDAR S85W 19 LKS. SET SMALL IRON PIN

Evidence of Subsequent Corner Restoration

Year of search 1922 By C. J. Bairk Hur Engineer Co. Hwy Dept. - BK # 147 in box "Field Books" Page 146 shows corner

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

V-17

Subsequent Corner Restoration

V 17

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By PLAT - BENA HARRY USHER 1903

PLAT - VILLAGE OF BENA JAMES MIDDLETON 1906

CERTIFICATE - GARY STEVENSON - 1982

Doc. # 263901

Set county cast iron monument.

7" Cedar S10 W 25.61';

8" Cedar S40E 41.00'

THIS CORNER IS BEING REVIEWED

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____