

Supervisor  
copy

U. S. Department of Agriculture  
FOREST SERVICE

P

Shippewa NATIONAL FOREST 213-4  
CORNERS OF THE PUBLIC SURVEY

T. 58-57 R. 26 4th Mer.

Meander Corner common to Sections  
3, and 34



Corner consists of a 4" Tamarack (not) in place  
State condition Rotted to ground - Stub left

Dimensions above ground 2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T57
R26
S3 W

T58
R26
S34 W



Mc
----

Mc
----

--

--

Species Tarn Cedar

Diameter 8" 8"

Bearing S20W N78W

Distance 3 LKS 7 LKS

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Checks with G.L.O. Notes

Charles J. Knoblauch  
(Signature)

7/20/37  
(Date)

Jr. Forester  
(Title)

Tamarack 131  
is broken off and leans  
against cedar  
Another metal location poster is  
on 5 inch wh. cedar 8 ft in which  
corner bears N 39° E 54 KS

Corner again.

Give any further facts which will aid in finding this


.07 chains distant.

from which this Corner bears 978 E

side of tree

tree 8 inches diameter, on the East

Metal Location Poster is on a wht. cedar



(Make sketch of topography near Corner)