

U. S. Department of Agriculture  
FOREST SERVICE

123  
7-28-37  
A 23

F

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141-142 R. 30 5 Mer.

1/64(10ch.W.of 1/4 cor.) Corner common to Sections

31, 6, and

Corner consists of a 1" iron pipe w/brass cap. in place

State condition Good

Dimensions above ground 2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

AP3			
TR			
1213			


N W S E NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	No. B. Ts.		

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*H. E. Altman*  
H. E. ALTMAN  
(Signature)

Assistant Ranger  
(Title)

9/15/36  
(Date)

F-48

C.I.R.

ce-S.O.

Corner is in center of road bed.  
Corner again.

Give any further facts which will aid in finding this

chains distant.

1/2


from which this Corner bears

South

side of road

~~Mark~~ 7 inches diameter, on the North

Metal Location Poster is on a Fence post



(State stretch of topography near Corner)

Mer.

5

30

R.

T.141-142

A-2.3