



U. S. Department of Agriculture
FOREST SERVICE

B-25

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 25 S. 5

M.C. Corner common to Section

1, and

Corner consists of a not found (not in place)

State condition

Dimensions above ground

Sketch grooves, letters, figures, or notches, on proper form or

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper form and fill blanks below, giving bearings from Corner to Tree and Distances in Links.

M.C. Soil 142-25			
B.T.			

Species Cedar

Diameter 10"

Bearing S85°W

Distance 22

Do you believe this to be a genuine Land Office Corner?

If not, why?

Raymond T. DeTant
Raymond T. DeTant

(Signature)

Jr. Civil Engineer

(Title)

8-9-10

(Date)



... on County line

... line going south

Corner again.

Give any further facts which will aid in finding this

chain distant.

from which this Corner bears


0.22

1888

... on the

Location Poster is on a

R.T.



(and ...)

142

55

5

Mer.