

FOREST SERVICE

Z-3

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143-142 R. 26 W 5th Mer.

Corner common to Sections
(31) and 6

Corner consists of a (not) in place

State condition There is no post

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4	Rotted		

Species Cedar Cedar

Diameter 10" 8"

Bearing N 13° E S 32° W

Distance 13 lks. 20 lks.

Do you believe this to be a genuine Land Office Corner? ~~Yes~~

If not, why? Scars right age. Co.

One B.T. rotted and damaged but ties

in O.K.

D.R. Gibney

(Signature)

Jr. Forester


(Title)

10/25/37

(Date)

Corner again.
Gadar swamp. Old cuttings around corner
& chains along town line east of lake.

Give any further facts which will aid in finding the
chains distant
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)