

U. S. Department of Agriculture  
FOREST SERVICE

*Post  
V23*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *148N* R. *26W* *5th* Mer.

*1/4* Corner common to Sections *25*, and *36*

Corner consists of a *wood Post* (not) in place  
State condition *Rotted off at base*

Dimensions above ground \_\_\_\_\_ inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION

<i>1/4</i>		<i>1/4</i>	
<i>5</i>		<i>5</i>	
<i>25</i>		<i>36</i>	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *?*

If not, why? *Questionable whether corner is Land Office Corner. Corner established according to old L. O. Notes. No B.T.s found*

*Herbert Norman*

(Signature)

*Nov. 5, 1934*  
(Date)

*Tech. Foreman*  
(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears *due west*

side of *road*

tree *inches diameter*, on the *East*

Metal Location Poster is on a *white Post*



(Make sketch of topography near Corner)

T. 14 S. R. 26 W. S. 27 N. Mer. V-23