


Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_

Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed: \_\_\_\_\_

Monument: \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed: \_\_\_\_\_

Monument: \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed: \_\_\_\_\_

Monument: \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_


Location filed: \_\_\_\_\_

Monument: \_\_\_\_\_

Index No. V 11

CASS COUNTY LAND CORNER RECORD

T. 137 R. 29 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N<sup>14</sup> 33 Corner common to sections 28, 33



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument Post

Species	Bearing	Trees
<u>ASPEN</u>	<u>7AM</u>	
Diameter <u>8"</u>	<u>12"</u>	
Bearing <u>S25 1/2 E</u>	<u>N45 E</u>	
Distance <u>44 LKS.</u>	<u>62 LKS.</u>	

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Evidence of Subsequent Corner Restoration

Year of search 1998 By CCSO

Fd. in place 2" Alum. cap monument down 0.3' in bit. 1.2' N of E Co. Rd. 115. Top is marred & unreadable. Located 35.55' No. of Fe. Line

Cor. is approx. located down E of driveway North currently under construction and fence line South

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Red Oak</u>	<u>18"</u>		<u>47.62'</u>
<u>Bur Oak</u>	<u>5"</u>		<u>71.20'</u>
<u>Red Oak</u>	<u>3"</u>		<u>55.12'</u>
<u>Fence Cap</u>			<u>35.55'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument Corner GPS 9/18/02 CCSO  
Called pipe down 0.2 on E

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_