


Index No. L 9

CASS COUNTY LAND CORNER RECORD

T. 138 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 17 Corner common to sections 16, 17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

| Bearing Trees | |
|------------------------|--------------------|
| Species <u>N. PINE</u> | <u>N. PINE</u> |
| Diameter <u>18"</u> | <u>18"</u> |
| Bearing <u>N 80° E</u> | <u>S 53 3/4° W</u> |
| Distance <u>-</u> | <u>-</u> |

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

| | | | |
|----------------|-------|-------|-------|
| Species _____ | _____ | _____ | _____ |
| Diameter _____ | _____ | _____ | _____ |
| Bearing _____ | _____ | _____ | _____ |
| Distance _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 3-24-04 By D. Landecker #17008
Location filed CCRO # A000488140
Monument 1" iron pipe capped 17008
monument lies in the bed of Suede Lake
and at times could be under water.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

| | | | |
|------------------------|----------------|----------------|------------------------|
| Species <u>OAK</u> | <u>OAK</u> | <u>OAK</u> | <u>1/2" Iron Pipe</u> |
| Diameter <u>10"</u> | <u>10"</u> | <u>10"</u> | |
| Bearing <u>N 86° E</u> | <u>S 52° E</u> | <u>S 50° W</u> | <u>S 88° 23' 30" E</u> |
| Distance <u>26.45'</u> | <u>25.18'</u> | <u>68.90'</u> | <u>23.39'</u> |

Bearing Trees, Reference Objects

| | | | |
|-------|-------|-------|-------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

APR 2002 T. FREEMAN
CERT OF SVY SHOWS MON FOUND

Aug 2003 B. Grivna #17253
Cert. of Svy. shows Mon Found

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____