


T. 138 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

NE 32 Corner common to sections 28, 29, 32, 33



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	N. PINE	N. PINE	N. PINE	N. PINE
Diameter	<u>15"</u>	<u>16"</u>	<u>16"</u>	<u>12"</u>
Bearing	<u>N36E</u>	<u>N51W</u>	<u>S81 1/2 W</u>	<u>S73E</u>
Distance	<u>64 LKS</u>	<u>120 LKS</u>	<u>180 LKS</u>	<u>25 LKS</u>

Original Bearing Trees Found

Species			
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920's ? By Co Hwy Dept  
Location filed BK # 145 - Box - "Field Books"  
Monument 2" iron pipe, 3" Conc. & steel monuments  
North: west 60'

Evidence of Subsequent Corner Restoration

Year of search 1-1998 By J. WALKER MN/DNR  
1/2" ROD DOWN 0.5' IN E T.H. # 84, ON  
E OF TH # 84 WEST  
CERT. OF LOCATION Dec. # 408862

Bearing Trees, Reference Objects

Species			
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>S'LY STOP SIGN POST</u>	<u>N 60° E</u>	<u>40.54</u>
<u>NW COR ELEC JCT. BOX</u>	<u>S 45° E</u>	<u>57.49</u>
<u>STOP SIGN POST</u>	<u>S 65° W</u>	<u>49.92</u>

Subsequent Corner Restoration

Year surveyed Oct. 2003 By P. Trottier #41002  
Location filed \_\_\_\_\_  
Monument Cert. of Sur. shows mon. found  
July 2003 P. Trottier #41002  
Cert. of Sur. shows mon. found

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

January 1992 D. Landecker #17008  
Cert. of Survey shows monument found