


Index No. J 21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 14 Corner common to sections 11, 12, 13, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>
Diameter	<u>6"</u>	<u>5"</u>	<u>5"</u>	<u>7"</u>
Bearing	<u>N67W</u>	<u>S42W</u>	<u>S24E</u>	<u>N40E</u>
Distance	<u>10 LKS.</u>	<u>14 LKS.</u>	<u>9 LKS.</u>	<u>40 LKS.</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1937 AUG. By J.A. GREENHAUS - CCC
Location filed REMER LOOKOUT SITE SURVEY
Monument FA 2 1/2" IRON PIPE / CAP BY COUNTY

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1969
Found capped pipe in good condition 12" high
in E of road. Found FSLP 8" Tamarack
South side of road. Set 2" x 5' galvanized
steel monument filled with concrete
and capped with 3" stamped brass
tablet. Ties: 5" Tamarack S17W 54.7'; 6"
Tamarack S35 E 40'; 10" Tamarack N54W
98.8'; 6" Spruce S77W 77.3'.

Remonumentation certificate prepared _____

Filed at _____

By _____

Date _____