


T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 24 Corner common to sections 13, 24 AND 18, 19-14-30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>ROAK</u>	<u>W. PINE</u>	<u>J. PINE</u>	<u>ASPEN</u>
Diameter	<u>8"</u>	<u>4"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>N56E</u>	<u>N70 1/2 W</u>	<u>S52 1/2 W</u>	<u>S87 1/2 E</u>
Distance	<u>16 LKS</u>	<u>13 LKS</u>	<u>40 LKS</u>	<u>17 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By State Hist Dept.
Location filed R/W map in Recorder's office
Monument Corner is 344.9' E. of G assumed at fence corner.

Evidence of Subsequent Corner Restoration

Year of search 1988 By David Landecker
Found 2" iron monument with brass cap.

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Red Oak	Red Oak	N. Pine	Tamarack
<u>14"</u>	<u>8"</u>	<u>24"</u>	<u>6"</u>
<u>N 30 W</u>	<u>N 52 E</u>	<u>S 63 E</u>	<u>S 25 W</u>
<u>76.00'</u>	<u>46.44'</u>	<u>75.36'</u>	<u>61.84'</u>
<u>(1977 BT)</u>		<u>(1977 BT)</u>	

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc. # 311073