


Index No. A 11

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N<sup>14</sup> 4 Corner common to sections 4 and 33-143-27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>SPRUCE</u>	<u>SPRUCE</u>	
<u>6"</u>	<u>6"</u>	
<u>N49W</u>	<u>S24W</u>	
<u>6 LKS</u>	<u>27 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1998 By NLSEM RLS #25342  
Set a 2"x48" galv. steel pipe w/brass cap, 1200't SWly of RR. grade.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Bk Spruce	Cedar	Cedar	Steel
<u>8"</u>	<u>6"</u>	<u>6"</u>	<u>Sign Post</u>
<u>N49°E</u>	<u>S67°E</u>	<u>S49°W</u>	<u>East</u>
<u>35.24'</u>	<u>16.59'</u>	<u>9.61'</u>	<u>1.56'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

Filed at CCRO Dec. #412868

By NLSEM

Date \_\_\_\_\_