


T. 143 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 21 Corner common to sections 16, 21



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species TAM TAM  
Diameter 5" 5"  
Bearing S32E N31W  
Distance 1465 2765

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed ? By GEO. RALPH  
Location filed COUNTY SURVEY RECORD BOOK B P. 97  
Monument FWD OLD RT: 5" TAM NW 17'

Evidence of Subsequent Corner Restoration

Year of search 1925 By C. Hwy. Dept  
State RD # 4 BOOK 154 PG 17

also on microfilm - roll 115 BK 82 P. 36

Bearing Trees, Reference Objects

Species TAM TAM  
Diameter 4" 5"  
Bearing S52-30W N31-30W  
Distance 56.2' 49'

Bearing Trees, Reference Objects

Tam stump TAM  
4" 3"  
S W SOUTH  
56.2' 69.6'

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By L. Levelling RS 16089  
Set a 6" x 24" galv. steel pipe w/ brass  
cap. Set in E Co. RD. 135 and perpetuates  
the orig. GLO 1873 survey and the position  
indicated by Cass Co. Hwy. Dept.

REF TIES:

8" Tamarack N 54° W 68.54'  
Steel Signpost NORTH 16.86' (FS 54-9)  
6" Tamarack S 24° E 76.17'  
5" " S 4° W 70.17'

CERT. OF LOCATION 5/17/99  
DOC. # 412844

2004? L. Levelling # 16089  
Cert. of Sur. Shows steel man with brass cap