


T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
N¹/₄ 23 Corner common to sections 14, 23



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument POST

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species Tam TAM
 Diameter 4" 4"
 Bearing S70E N27E
 Distance 28 LKs 22 LKs

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 7 By Geo. Ralph
 Location filed COUNTY SURVEY RECORD BOOK B" P.97
 Monument FIND OLD 2" POST
also on microfilm - roll 115 BK82 P. 40

Evidence of Subsequent Corner Restoration
 Year of search 1925 By Co Hwy Dept
State RD # 4 BOOK 154 PAGE 22
Corner

Bearing Trees, Reference Objects
 Species TAM TAM.
 Diameter 3" 3"
 Bearing N30W S29E
 Distance 39' 37.7'

Bearing Trees, Reference Objects
Tam TAM
3" 3"
SE NW
37.7' 39.0'
6LO BT 6LO BT

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search 1999 By L. Leuelling RLS 16089
Set .6" x 24" galv. steel pipe w/ brass
cap, perpetuating the orig. GLO corner
recovered by Cass Co. in the 1910-1915 period
located E of Co RD. 135 and 267' West of
a fwd. culvert.
 - REF TIES:
 Steel signpost NORTH 28.00'
 6" Tamarack S14°E 81.99'
 6" Tamarack S5°W 76.32'
 CERT. OF LOCATION 5/17/99
 DOC. # 412846