


T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
N 14 20 Corner common to sections 17, 20



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Bearing Trees

Species	<u>Tam</u>	<u>Tam</u>
Diameter	<u>5"</u>	<u>6"</u>
Bearing	<u>S44E</u>	<u>N47E</u>
Distance	<u>21KS</u>	<u>15KS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 7 By Geo. Ralph

Location filed County Survey Record Book B P. 97

Monument Fnd Old Post - Old B.T.S: 8" Tam N31-30 E 116', 5" Tam S52-30 E 134'

also on microfilm - roll 115 BK 82 P. 34

Bearing Trees, Reference Objects

Species	<u>TAM</u>	<u>CEDAR</u>
Diameter	<u>6"</u>	<u>6"</u>
Bearing	<u>N4E</u>	<u>S27-30E</u>
Distance	<u>38.6'</u>	<u>43.6'</u>

Evidence of Subsequent Corner Restoration

Year of search 1925 By Co Hwy Dept

State Rd #4 Book 154 Page 15

Corner

Bearing Trees, Reference Objects

<u>Tam stump</u>	<u>Tele. pole</u>
<u>6"</u>	
<u>NE</u>	<u>SW</u>
<u>38.6'</u>	<u>32.5'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By L. LEUELLING

FND Old B.T. Tamarack stump and
culv. & set a .6 x 24" Galv. steel pipe
w/ stamped cap. This perpetuates the
orig. GLO 1/4 cor. in E Co. Rd. 135

REF. TIES:

(C.C. 1915) Tam. stump N 4° E 11.765m (38.60')
6" Ash N 12° E 13.128m (43.07')
5" Ash N 58° E 24.894m (81.67')
Steel signpost South 5.740m (18.83')
5" Aspen S 67° W 27.704m (90.89')

CERT. OF LOCATION 5-30-99
Doc. No. 413422