


T. 143 R. 28 M. 5TH Coordinates: X _____ Y _____
E114 25 Corner common to sections 25 AND 30 - 143-27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1879
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Sugar Maple</u>	<u>Sugar Maple</u>	_____
Diameter	<u>10"</u>	<u>12"</u>	_____
Bearing	<u>N30E</u>	<u>S75W</u>	_____
Distance	<u>17 LKS</u>	<u>18 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By JOHN CUKO
Location filed COUNTY SURVEY RECORD BOOK B' P 220-242
Monument FIND OLD GOVT B.T. 12" SUGAR S75W 11 LKS
SET IRON
1920, J. H. FLYNN COUNTY BOOK C' P 340 FIND I.M.
1916 - also on microfilm - roll 115 BK 77 P 28-2943

Bearing Trees, Reference Objects P. 49 set I.M.

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1975 By CO HWY DEPT
CORD # 4
2" (1/2" in place
4-7-80 set 1" rod for corner

Bearing Trees, Reference Objects

Birch	<u>Poplar</u>	<u>Poplar</u>	_____
<u>6"</u>	<u>8"</u>	<u>12"</u>	_____
<u>N</u>	<u>NW</u>	<u>SW</u>	_____
<u>99.0'</u>	<u>90.3</u>	<u>112.8</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1986 Certificate - Walter Curo
Doc. # 291486
Found 2 1/2" iron pipe flush with surface
of County Road #4. Set 2x24 iron
pipe with brass cap 8" below road
surface with RR spike on top.
Power pole N45W 52.04';
6" Balsam S42W 36.18';
6" Maple S38E 138.10';
8" W. Oak N15E 64.17'.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____