


T. 144 R. 26 M. 5TH Coordinates: X _____ Y _____
N1419 Corner common to sections 18, 19



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Tam</u>	<u>Tam</u>	_____	_____
Diameter	<u>4"</u>	<u>3"</u>	_____	_____
Bearing	<u>S42E</u>	<u>N12W</u>	_____	_____
Distance	<u>22 LKS</u>	<u>40 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1971 By William OKerman
Location filed _____
Monument Set 2" x 60" galvanized steel pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Tamarack</u>	<u>Tamarack</u>	<u>Tamarack</u>
Diameter	<u>7"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>N85E</u>	<u>S61W</u>	<u>N13E</u>
Distance	<u>15.20'</u>	<u>20.90'</u>	<u>18.90'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1971 - FILED IN 1979
Doc. # 258568