


T. 144 R. 31 M. 5th Coordinates: X _____ Y _____

W 1/16 Corner common to sections 13, 24



EXISTING SURVEYS

Original Government Survey

Year surveyed 9/1930, H.D. Craig, U.S. Surveyor, GLO
 Original monument Set 1"x 3' iron pipe w/brass cap W1/16 S 13
S 24
Notes page 31, at proportionate distance and witnessed 1930

Bearing Trees

Species	<u>Norway Pine</u>	<u>Jack Pine</u>	_____
Diameter	<u>8"</u>	<u>4"</u>	_____
Bearing	<u>N 12°30' E</u>	<u>S 72° E</u>	_____
Distance	<u>148 links</u>	<u>156 links</u>	_____

Original Evidence Found

Year of search _____ by _____
 Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 6/1985 By G. Brama, USFS
 Location filed: USFS Field Book 1, page 30
 Monument: Found GLO pipe with brass cap up 3", leaning, on back of ditch on E. side of Lake Thirteen Rd. and adds the following.

Bearing Trees, Reference Objects

Species	<u>Steel Sign</u>	_____	_____
Diameter	<u>Post</u>	_____	_____
Bearing	<u>North</u>	_____	_____
Distance	<u>2.5'</u>	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 3/2004 By P.B. Schoborg, LS 14700
 Location filed: Certificate of Survey for Piprude, #2359
 Monument: Iron monument inplace

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed: _____
 Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____

