


T. 145 R. 29 M. 574 Coordinates: X _____ Y _____
NE 25 Corner common to sections 24, 25 and 19, 30 - 145-28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Species	Bearing	Tree	Distance
<u>N. Pine</u>	<u>N 174° W</u>	<u>10 LKS</u>	
<u>N. Pine</u>	<u>N 52° E</u>	<u>160 LKS</u>	
<u>N. Pine</u>	<u>S 88° W</u>	<u>25 LKS</u>	
<u>N. Pine</u>	<u>S 75° E</u>	<u>58 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1974 By RLM

Location filed Sec. of State

Monument End 5" concrete man w/ brass cap 2" under S. edge of Hwy 2 set by T145N RLS # 6807

Evidence of Subsequent Corner Restoration

Year of search 1979 By DNR-Engineering

Map & notes in file

Found 3" brass cap monument 0.15' below surface of Hwy 17.1' S. of G Hwy 2

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

524 519
525 530
1968
RLS # 6807

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>J. Pine</u>	<u>10"</u>	<u>N 55° E</u>	<u>155.95'</u>
<u>Roak</u>	<u>8"</u>	<u>S 40° E</u>	<u>134.84'</u>
<u>Roak</u>	<u>9"</u>	<u>S 36° W</u>	<u>101.90'</u>
<u>Red. Pine</u>	<u>21"</u>	<u>N 46° W</u>	

1968 USFS TIES

R-25

Subsequent Corner Restoration

Year surveyed 1986 By Walt Curo

Location filed Corner Certificate - Doc # 291635

Monument End brass cap set in concrete as per previous surveys.

Corner is 171' S. of G. US. Hwy 2, down 2"

24" N. Pine N 46° W 197.95' (1968 tie)

5" Burr oak N 15° E 113.55'

10' Red oak S 40° E 134.84' (1968 tie)

5" N. Pine S 70° W 140.32'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - PORTAGE LAKE

R. L. WARNER 1925

Certificate - Walt Curo - 1986

MARCH 1999, T. LARSON - MN/DOT - FOUND MON. & WITNESSES

CASS Co NORTH HAVEN N = 91657.449 m
E = 146244.148 m

11/03 - Landecker & Assoc Cert of Survey indicates found monument.