


T. 145 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

E 1/4 8 Corner common to sections 8, 9



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Black Pine</u>	<u>Black Pine</u>
Diameter	<u>10"</u>	<u>10"</u>
Bearing	<u>N 72° W</u>	<u>N 52° E</u>
Distance	<u>8 links</u>	<u>32 links</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 8/1933 By W.W. Bandy, Surveyor, GLO  
Location filed: MN Historical Society, Notes page 76 1/4  
Monument: Set 1"x 3' iron post with brass cap S 8 | S 9  
At proportionate position, no remaining evidence of original corner and witnessed as follows. 1933

Evidence of Subsequent Corner Restoration

Year of search 12/1933 By J.A. Gielhaug, Engineer, CCC  
Location filed: USFS Form 874-9  
Monument: Brass capped 1.5" Iron pipe up 6" and witnesses, probably 1933.

Bearing Trees, Reference Objects

Species	<u>Jack Pine</u>	<u>Jack Pine</u>
Diameter	<u>8"</u>	<u>7"</u>
Bearing	<u>N 87° E</u>	<u>N 22 3/4° W</u>
Distance	<u>79 links</u>	<u>10 links</u>

Bearing Trees, Reference Objects

Species	<u>Jack Pine</u>	<u>Jack Pine</u>
Diameter	<u>6"</u>	<u>6"</u>
Bearing	<u>N 35° W</u>	<u>N 89° E</u>
Distance	<u>9 3/4 links</u>	<u>78 1/4 links</u>

Subsequent Corner Restoration

Year surveyed 10/1965 By J. Ekstrom, USFS  
Location filed: USFS Book 2, page 6  
Monument: Found GLO iron with brass cap and witnesses as follows.  
Jack Pine snag, N 87° E, 52.14'(1933)  
Jack Pine snag, N 23° W, 6.60'(1933)  
12" Norway Pine, N 5° W, 133.25' scribed  
12" Oak, S 53° E, 60.0' scribed

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed: \_\_\_\_\_  
Monument: \_\_\_\_\_

4/1966, A. Wells, USFS  
USFS Book 2, page 6  
added the following witness.  
16" Red Pine, N 88° E, 133.0' tree scribed  
  
8/1967, J. Ekstrom, USFS  
USFS Book 2, page 6 T145N R30W  
Brass cap was removed by road construction 1/4  
set a 6" concrete cylinder with bronze tablet, S 8 | S 9  
6" below shoulder of road and witnessed. 1967  
4" Cedar Post, N 55° W, 6.7' 54-4 sign RLS No. 6807

