


T. 145 R. 30 M. 5th Coordinates: X _____ Y _____

MC #3 Corner common to sections 36 and 31-145-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Cedar</u>	<u>Cedar</u>
Diameter	<u>6"</u>	<u>10"</u>
Bearing	<u>N 29° W</u>	<u>N 25° E</u>
Distance	<u>10 links</u>	<u>23 links</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 6/1933 By W.W. Bandy, Surveyor, GLO
 Location filed: MN Historical Society, notes page 3 WC
 Monument: Set 1"x 36" Iron Pipe with brass cap at proportionate distance, on N. shore of Sucker Lake, this falls on unsafe ground, at 0.5 chain(33.00') N. set WC and marked new witnesses as follows.

Bearing Trees, Reference Objects

Species	<u>Cedar</u>	<u>Balm of Gilead</u>
Diameter	<u>5"</u>	<u>4"</u>
Bearing	<u>N 58 3/4° E</u>	<u>N 9 3/4° W</u>
Distance	<u>114 links</u>	<u>57 links</u>

Evidence of Subsequent Corner Restoration

Year of search 1/1962 By R.H. McDonald, USFS
 Location filed: USFS Book 1, page 4
 Monument: Found GLO brass cap no WC on cap as noted, lists witnesses as follows.

Bearing Trees, Reference Objects

Species	<u>Cedar</u>	<u>Cedar</u>	<u>Ash</u>
Diameter	<u>7"(1933)</u>	<u>7"</u>	<u>8"</u>
Bearing	<u>N 59° E</u>	<u>N 34°30' E</u>	<u>N 63° E</u>
Distance	<u>75.24'</u>	<u>73.0'</u>	<u>35.4'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed: _____
 Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____

