

U. S. Department of Agriculture
FOREST SERVICE

A-13
Not filmed?

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 26 5 Mer.
Section _____ Corner common to Sections

3, 4, 33, and 34

Corner consists of a iron pipe (M) in place

State condition very good

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N O N E			
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing N O N E

Distance _____

Do you believe this to be a genuine Land Office Corner? No.

If not, why? because this iron pipe has no brass cap.

R. T. DeFaut
Raymond T. DeFaut

(Signature)

Jr. Civil Engineer

(Title)

2-28-40

(Date)

Faint, illegible text on a ruled background, possibly bleed-through from the reverse side of the page.

Corner again.

Give any further facts which will aid in finding the

chain distant.


14

from which this Corner bears North

side of Cedar Snag

tree 12 inches diameter, on the North

Metal Location Post is on a Cedar Snag



(Make sketch of topography near corner)