

U. S. Department of Agriculture  
FOREST SERVICE

*Posted*

G22

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143N. R. 31W. 5<sup>th</sup> Mer.

Sixteenth Corner common to Sections  
12, \_\_\_\_\_, and \_\_\_\_\_


Corner consists of a *Br. cap iron pipe* (~~rod~~) in place  
State condition *good*

Dimensions above ground *1" x 1/4"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *J. Pine* *J. Pine*

Diameter *9"* *6"*

Bearing *N. 61° 30' W.* *S. 18° 30' E.*

Distance *95* *111*

Do you believe this to be a genuine Land Office Corner? *Yes.*

If not, why? \_\_\_\_\_

*Dorman J. Sutton*

(Signature)

*Compassman*

(Title)

*11-9-34*  
(Date)

-----

-----

-----

-----

-----

-----

-----

-----


-----

-----

Corner again.

Give any further facts which will aid in finding this  
 ----- chains distant.  
 ----- from which this Corner bears  
 ----- side of  
 ----- tree ----- inches diameter, on the  
 ----- Metal Location Poster is on a

*None*



(Make sketch of topography near Corner)

Mer. 6-22

T. 143N R. 31W 5th