

U. S. Department of Agriculture  
FOREST SERVICE

*Posted*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144 N* R. *36 W* *5th* Mer.

*Meander* Corner common to Sections  
*11*, and *12*

Corner consists of a *Brass Lead Pipe* (not) in place  
State condition *Good*

Dimensions above ground *19* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

*M.C.*  
*9.12*

*B.T.*

Species *N. Pine*

Diameter *20"*

Bearing *N. 13° E.*

*LN* Distance *68 1/2*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_


*J.A. Gjelhaug*  
(Signature)

*Tech. Eng.*  
(Title)

*9/3/39*  
(Date)

Corner again.

Metal Location Poster is on a tree ..... inches diameter, on the side of ..... from which this Corner bears ..... chains distant.  
 Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)